



Machine	Explode	Code	Description	Stocked Line
P109	1	n/a	Griddle Plate	n/a
P109	2	N497	Heating Element	✓
P109	3	N125	300c Thermostat	✓
P109	4	n/a	Insulation Clamp	n/a
P109	5	N126	120c Thermal Cut Out	✓
P109	6	N150	Plug & Lead	✓
P109	7	n/a	Feet	n/a
P109	8	N129	Dial	✓
P109	9	N486	Indicator Light	✓
P109	10	N498	Drip Tray	✓
P109	11	n/a	Element Clamp	n/a